



D5490

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of: Bishop et al.)
Serial No.: 10/775,619)
Filed: February 10, 2004) Group Art Unit: 3747
For: Engine Speed Stabilizer)
Using Fuel Rate Control)

RESPONSE TO NOTICE TO FILE CORRECTED APPLICATION PAPERS

Mail Stop Missing Parts
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

In response to the Notice To File Corrected Application Papers mailed May 11, 2004 in the above-identified application, transmitted herein are formal drawings in accordance with 37 CFR 1.84.

Respectfully submitted,

Dennis Kelly Sullivan
Registration No. 26,510

Warrenville, IL 60555
Date: July 29, 2004
Telephone: (630) 753-2311

CERTIFICATE OF FIRST CLASS MAILING UNDER 37 CFR 1.8 (a)

I hereby certify that this RESPONSE TO NOTICE TO FILE CORRECTED APPLICATION PAPERS is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Mail Stop Missing Parts, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on or before 7/29/04.

7/29/04
Date

Cathi Majewski

JFW



UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE
 United States Patent and Trademark Office
 Address: COMMISSIONER FOR PATENTS
 P.O. Box 1450
 Alexandria, Virginia 22313-1450
 www.uspto.gov

APPLICATION NUMBER	FILING OR 371 (c) DATE	FIRST NAMED APPLICANT	ATTORNEY DOCKET NUMBER
10/775,619	02/10/2004	Kevin P. Bishop	D5490

30409
 INTERNATIONAL ENGINE INTELLECTUAL PROPERTY COMPANY
 4201 WINFIELD ROAD
 P.O. BOX 1488
 WARRENVILLE, IL 60555

CONFIRMATION NO. 1571

FORMALITIES LETTER



OC000000012588386

Date Mailed: 05/11/2004

NOTICE TO FILE CORRECTED APPLICATION PAPERS

Filing Date Granted

An application number and filing date have been accorded to this application. The application is informal since it does not comply with the regulations for the reason(s) indicated below. Applicant is given TWO MONTHS from the date of this Notice within which to correct the informalities indicated below. Extensions of time may be obtained by filing a petition accompanied by the extension fee under the provisions of 37 CFR 1.136(a).

The required item(s) identified below must be timely submitted to avoid abandonment:

- Replacement drawings in compliance with 37 CFR 1.84 and 37 CFR 1.121 are required. The drawings submitted are not acceptable because:
 - Numbers, letters, and reference characters on the drawings must measure at least 0.32 cm (1/8 inch) in height. See Figure(s) 6.

Replies should be mailed to: Mail Stop Missing Parts
 Commissioner for Patents
 P.O. Box 1450
 Alexandria VA 22313-1450

*A copy of this notice **MUST** be returned with the reply.*

Customer Service Center

Initial Patent Examination Division (703) 308-1202

PART 2 - COPY TO BE RETURNED WITH RESPONSE